



Environmental Management Consulting, Inc.

Facility Safety Audit
Platteville School District
October 10, 2005

On September 27, 2005, Todd J. Swenson of Environmental Management Consulting, Inc. (EMC) performed a safety audit of the Platteville School District's Elementary Schools.

This audit was intended for use as a guide to identify the types of safety violations the Department of Commerce would be looking for in the case of an inspection. It is also a way for you to recognize items that may lead to possible injuries to employees or students. Please keep in mind that the intention was not to identify every violation that might be present, but to give you an idea of the types of correctable safety violations that do exist in the Schools. This report should be filed with the Health & Safety Programs.

If you should have any questions regarding this report please do not hesitate to contact EMC at 1-800-279-2020.

SAFETY DEFICIENCIES

The following areas could use improvement:

Wilkins Elementary School

<u>Location</u>	<u>Comments</u>
Room 17	General housekeeping. (photo 1)
Outside Equipment Storage	Flammable liquids should not be stored with combustibile materials. (photo 2)

Gray Early Learning Center

<u>Location</u>	<u>Comments</u>
Janitor Closet at Office	Shelf unstable and above doorway. Recommend removing shelf. (photo 3)
Boiler Room	Ground prong missing on extension cord. (photo 4)

Securing Safer Futures...

Gray Early Learning Center (cont.)

<u>Location</u>	<u>Comments</u>
Attic Access	Fixed ladder extension missing. Fixed ladder should extend 3 ½' above landing. (photo 5)
Boiler Room	Non-skid strips required on stairs. (photo 6)
Boiler Room	Electrical panel missing faceplate. (photo 7)
Hallway	Fire extinguisher not properly identified. Recommend installing sign on wall above extinguisher. (photo 8)

Westview Elementary School

<u>Location</u>	<u>Comments</u>
Cust. A	3 ft. clearance necessary in front of electrical panels. (photo 9)
Room 14	Television must be stabilized and secured to cart. (photo 10)

Wilkins Elementary School
Room 17
Photo 1

- General housekeeping.



Wilkins Elementary School
Outside Equipment Storage
Photo 2

- Flammable liquids should not be stored with combustibles.




Gray Early Learning Center
Janitor Closet at Office

Photo 3 - Shelf unstable and above doorway. Recommend removing shelf.



Gray Early Learning Center
Boiler Room

Photo 4 - Ground prong missing on extension cord.



Gray Early Learning Center

Attic Access

Photo 5

- Fixed ladder extension missing. Fixed ladder should extend 3 ½' above landing.




Gray Early Learning Center
Boiler Room
Photo 6

- Non-skid strips required on stairs.



Gray Early Learning Center
Boiler Room
Photo 7

- Electrical panel is missing faceplate.



Gray Early Learning Center
Hallway
Photo 8

- Fire extinguisher not properly labeled.
Recommend installing sign on wall above extinguisher.



Westview Elementary School
Cust. A
Photo 9

- 3 ft. clearance necessary in front of electrical panels.



Westview Elementary School
Room 14
Photo 10

- Television must be stabilized and secured to cart.

